# BrightAuthor 2.2.0. 39

June 9, 2011

This release includes bug fixes and improvements.

Improvements and Bug Fixes

- Added support for MOV and MP4 videos
- Changed minimum firmware requirement to 3.5.68
- Changed default audio to HDMI Audio
- Fixed: Link Zones event now uses correct icon
- Fixed: BrightAuthor displays correct message when you try open a second instance
- Fixed: Units with restricted download times now report status correctly to BrightSign Network

BrightAuthor Requirements

- PC with Windows XP or Vista or Windows 7, plus Microsoft .Net Framework 3.5 or later
- BrightSign HD110, HD210, HD210w, HD410, HD1010, or HD1010w
- Firmware version 3.5.68 or later

Getting Help and Providing Feedback

Before you start using BrightAuthor 2.2, please download the Quick Start Kit and visit the Tutorial Videos page. To help us get the most out of testing, please provide feedback in the BrightSign forum.

If you have any questions, please contact support@brightsign.biz.